

FORD 4R100 "UPDATE HANDBOOK"

INDEX

PRELIMINARY DIAGNOSTIC INFORMATION	3
IDENTIFICATION TAG LOCATION AND INFORMATION	6
LUBE ORIFICE PLUGAND EXTENSION HOUSING INFORMATION	9
MANUAL LEVER IDENTIFICATION	11
COOLER BYPASS VALVE DIFFERENCES	12
PUMP COVER VALVES EXPLODED VIEW	14
PUMPSTATOR DIFFERENCES	15
COAST CLUTCH HOUSING DIFFERENCES	16
OVERDRIVE ROLLER CLUTCH DIFFERENCES	18
OVERDRIVE FRICTION DIFFERENCES	19
VALVE BODY CHECKBALL LOCATIONS	20
LOWER VALVE BODY SPACER PLATE IDENTIFICATION	21
MAIN CASE CHECKBALL LOCATIONS	22
ALL VALVE BODIES EXPLODED VIEWS	23
ELECTRONIC COMPONENT RESISTANCE CHARTS	25
SOLENOID CONNECTOR PIN IDENTIFICATION	27
TROUBLE CODE CHARTAND DESCRIPTION	29
POWER TAKE OFF DESCRIPTION AND OPERATION	34
"NON-PTO" AND "PTO" HYDRAULIC DIFFERENCES	38
MAIN CASE CENTRAL LUBE ADDED	39
SPACER PLATE DIFFERENCES PTO AND NON-PTO	40
"NON-PTO" AND "PTO" PUMP DIFFERENCES	50
PWM SOLENOID PACK RESISTANCE CHART	56
SIX PINION FORWARD AND REAR PLANETARY CARRIERS	57
NEW DESIGN SUN SHELL	60
INTERMEDIATE DIODE FREEWHEEL FAILURE	64
HYDRAULIC PASSAGE IDENTIFICATION	67
NO TCCAT LESS THAN 30% THROTTLE	77
NEW "SPECIAL" 4R100 CASE FOR E4OD REPLACEMENT	82
ARTICLE ON PTO OPERATION	97
PTO OIL CIRCUIT DIAGRAMS	100

AUTOMATIC TRANSMISSION SERVICE GROUP 18639 S.W. 107 AVENUE MIAMI, FLORIDA 33157 (305) 670-4161

Copyright © ATSG 2005



INTRODUCTION

FORD 4R100 "UPDATE HANDBOOK"

Since the introduction of the 4R100 transmission in model year 1998, there have been many engineering changes to improve Pleaseability, Reliability and Durability concerns. These changes have affected most every part used in this transmission. This "Update Handbook" will explain each change, the reason for the change, and any parts interchangeability concerns created by the change, along with any part numbers needed to update your transmission.

We wish to thank Ford Motor Company for the information and some illustrations that have made this booklet possible.

No part of any ATSG publication may be reproduced, stored in any retrieval system or transmitted in any form or by any means, including but not limited to electronic, mechanical, photocopying, recording or otherwise, without *written* permission of Automatic Transmission Service Group. This includes all text illustrations, tables and charts.

The information and part numbers contained in this booklet have been carefully compiled from industry sources known for their reliability, but ATSG does not guarantee its accuracy.

Copyright © ATSG 2005

DALE ENGLAND FIELD SERVICE CONSULTANT

WAYNE COLONNA TECHNICAL SUPERVISOR

PETER LUBAN
TECHNICAL CONSULTANT

JON GLATSTEIN TECHNICAL CONSULTANT

JERRY GOTT TECHNICAL CONSULTANT

GERALD CAMPBELL TECHNICAL CONSULTANT JIM DIAL TECHNICAL CONSULTANT

ED KRUSE TECHNICAL CONSULTANT

GREGORY LIPNICK
TECHNICAL CONSULTANT

DAVID CHALKER TECHNICAL CONSULTANT

ROLAND ALVAREZ TECHNICAL CONSULTANT

MIKE SOUZA TECHNICAL CONSULTANT

AUTOMATIC TRANSMISSION SERVICE GROUP 9200 S. DADELAND BLVD. SUITE 720 MIAMI, FLORIDA 33156 (305) 670-4161

ATSG

Technical Service Information

FORD 4R100 PRELIMINARY INFORMATION

CHANGE: Beginning at the start of production for 1999 models, Ford Motor Company introduced a new transmission in some F250, F350, F450 and F550 Super Duty Trucks, equipped with the 5.4L, 6.8L and 7.3L engines. Basically the new 4R100 is a revised version of the previous E4OD transmission with a Power-Take-Off (PTO) window on the side of the case (See Figure 1). The revisions that have occured however, have created many major engineering changes that have affected many internal and external parts that will affect service.

REASON: Provided a PTO option for Ford Motor Company.

PARTS AFFECTED:

- (1) TRANSMISSION CASE Now has a PTO window added to the left side of the case directly behind the front pump area, and a Turbine Speed Sensor has been added at the top of the case and triggered by a revised coast clutch drum (See Figure 2). Another change to the rear of the case is the addition of a Lube Orifice Plug to the Rear of the case, as shown in Figure 4, which also changes the extension housings.
- (2) TURBINE SPEED SENSOR Added to the top front of the case on some models, as shown in Figure 2. We have also provided you with the resistance readings and OEM part numbers on both Turbine Speed Sensors, as the PTO and Non-PTO models use different sensors. Refer to Figure 2 for turbine speed sensor information.
- (3) OUTPUT SHAFT SENSOR Output Shaft Speed sensor was added to the top of the extension housing on some models, as shown in Figure 2. OSS is triggered by an added rotor pressed onto the output shaft, which requires a new tool to position the speed rotor properly *if* it is removed during overhaul, as shown in Figure 3. The park gear is also now pressed onto the output shaft, and the number 13 thrust washer has been changed to a thrust bearing as shown in Figure 3. We have provided you with the resistance reading and the OEM part numberfor the output shaft speed sensor. Refer to Figure 2 for output shaft speed sensor information.
- (4) LUBE ORIFICE PLUG Added to the rear of the case in the lube circuit to provide added lubrication to the extension housing bushing on 2WD models. To retain common cases the 4WD models will also have the lube orifice plug installed, as well as E4OD cases produced after July 24, 1997. Lube Orifice Plug is available under OEM part number F81Z-7E380-AA, and should be replaced on rebuild. Refer to Figure 4.
- (5) EXTENSION HOUSING Has an added boss or shoulder to retain the lube orifice plug in position in the transmission case, as shown in Figure 5. Notice that the 6.8L and 7.3L, 2 wheel drive extension housing has added a new passage to the extension housing bushing, much like the 4L80-E. All 4R100 and E4OD transmissions equipped with the lube orifice plug *must* use an extension housing with the shoulder or boss. Failure to do so could blow the lube orifice plug out and exhaust all lube oil, which would be catastrophic. Refer to Figure 5.

Continued on next Page.



PARTS AFFECTED: (Continued)

- (6) MANUAL SHIFT LEVER There are two different external shift levers for this unit, one for Non-PTO transmissions and one for transmissions with the PTO option, as shown in Figure 6. We have provided you with the "Stamping" number as well as the OEM part number for both, as shown in Figure 6.
- (7) COOLER BYPASS VALVE Similar to the Cooler Bypass Valve on the E4OD that provides lubrication to the transmission in case of blocked or partially blocked coolers. We have given you OEM part numbers for both and both bypass valves are illustrated in Figure 7.
- (8) TRANSMISSION COOLERS Most F-Series vehicles over 8500 GVW equipped with the 4R100 transmission have an external "Oil-To-Air" cooler *only*. Due to the internal design of the "Oil-To-Air" cooler, it cannot be adequately flushed to remove contaminants, and requires replacement during transmission rebuild. The only exception is that F-Series vehicles over 8500 GVW equipped with the 5.4L engine also uses a radiator "In-Tank" cooler in addition to the "Oil-To-Air" cooler. Refer to Figure 8 for transmission cooler information.
- (9) FRONT PUMP COVER The pump cover is basically the same as the E4OD, but has a different valve line-up in the Converter Clutch Control Valve bore. The gasoline applications all have an "On-Off" lock-up solenoid and the 7.3L diesel applications all have a Pulse Width Modulated (PWM) lock-up solenoid. This changes the Converter Clutch Control Valve line-ups in the pump cover, as shown in Figure 9.
- (10) FRONT PUMP STATOR SHAFT With the addition of the PTO gear on the front of the coast clutch drum, it was necessary to move the coast clutch sealing ring grooves up on the pump stator shaft to accommodate the coast clutch drum moving. There are currently three different Pump Stator Shafts used in production and all three are illustrated in Figure 10. One is the current E4OD shaft which is used with the "Cast Iron" coast clutch drum with 5.4L and 6.8L engines *without* the PTO option. Two is the shaft with the relocated sealing rings and a bushing in the pump tower, which is used with the "Stamped Steel" coast clutch drum with 5.4L and 6.8L engines *without* the PTO option. Third is the shaft with the relocated sealing rings and a caged needle bearing in the pump tower, which is used with the "Stamped Steel" coast clutch drum with 6.8L and 7.3L engines *with* the PTO option. Refer to Figure 10.
- (11) COAST CLUTCH DRUM AND STEELPLATES There is now a revised "Stamped Steel" coast clutch drum introduced with the 4R100 transmission. There are currently three different coast clutch drums used in production and all three are illustrated in Figure 11. One is the current E4OD coast clutch drum which is "Cast Iron" and uses the current steel plates. Two is the new design "Stamped Steel" coast clutch drum without the PTO gear pressed on it and uses a new design coast clutch steel plate to accommodate the new drum. Third is the new design "Stamped Steel" coast clutch drum with the PTO gear pressed on it and uses the new design coast clutch steel plates to accommodate the new drum. The new design "Stamped Steel" coast clutch drum now has the overdrive roller clutch inner cam made on the drum and the overdrive sun gear is pressed into the new design drum, which changes the assembly process of the overdrive roller clutch. Refer to Figure 11.
- (12) COAST CLUTCH PISTON The coast clutch piston in the new design coast clutch drum is now a stamped steel, molded rubber seals assembly and is illustrated in Figure 12. The new design piston assembly requires a new seal protector tool, Rotunda No. 307-387, to install the piston and seal assembly into the new design stamped steel coast clutch drum (See Figure 12).

Continued on next Page.



PARTS AFFECTED: (Continued)

- (13) OVERDRIVE ROLLER CLUTCH The overdrive roller clutch inner cam is now made onto the new design coast clutch drum, instead of being splined like the previous models were, and is illustrated in Figure 13. The new design overdrive roller clutch assembly is now assembled onto the inner cam on the new design drum. The overdrive roller clutch outer race is still located in the overdrive ring gear next to the overdrive carrier and the number 13 thrust washer between the two is now plastic, but the cage and roller assembly are now assembled over the inner race on the new design coast clutch drum. Refer to Figure 13.
- (14) OVERDRIVE FRICTION PLATES Now have wider teeth to accommodate the new design stamped steel coast clutch drum assembly when it is used, as illustrated in Figure 14.
- (15) VALVE BODY CHECKBALL LOCATIONS Valve body checkball locations are illustrated in Figure 15 and now has two 1/4" checkballs and two 5/16" checkballs. This of course changes the lower valve body spacer plate as illustrated in Figure 16. The new design spacer plate has only one hole over the bathtub where the checkball was removed. The case checkball locations remain the same as the 1996-Up configuration, and this illustration is included for reference and shown in Figure 17.
- (16) VALVE LINE-UPS IN VALVE BODY Have changed from the previous models and are illustrated in Figure 18, with a valve description and legend shown in Figure 19.
- (17) SOLENOID BODY There are now two different Solenoid Bodies, depending on whether you have a gasoline or diesel model. Since the diesel models now have a Pulse Width Modulated (PWM) converter clutch application, the resistance on the converter clutch solenoid in the Solenoid Body is going to be different. We have included the OEM part numbers for both solenoid bodies and resistance charts for all solenoids in Figure 20, and you will find solenoid application and pin function charts in Figures 21 and 22.
- (18) TROUBLE CODES Abbreviations are listed in Figure 23 and OBD II Trouble Codes are listed in numerical order in Figures 24 through 28.

INTERCHANGEABILITY:

All of the parts listed above are model sensitive, and some of the parts listed above cannot be intermixed with E4OD parts. With this unit you will have to be very carefull if replacement of the various components becomes necessary.

SERVICE INFORMATION:

Turbine Shaft Speed Sensor (PTO Models Only)	F81Z-7M101-BA
Turbine Shaft Speed Sensor (Non-PTO Models Only)	F81Z-7M101-AA
Output Shaft Speed Sensor (All Models)	F81Z-7M101-AA
Lube Orifice Plug (Plastic)	F81Z-7E380-AA
External Manual Shift Lever (With PTO Option)	F81Z-7A256-AA
External Manual Shift Lever (Without PTO Option)	F7UZ-7A256-BB
Cooler Bypass Valve Assembly	F81Z-7H322-AA
Coast Clutch Piston (New Design)	F81Z-7A262-AA
Solenoid Body Assembly (Gasoline Engine Only)	F81Z-7G391-BA
Solenoid Body Assembly (Diesel Engine Only)	F81Z-7G391-AB
Overdrive Roller Clutch And Cage Assembly	F81Z-7A089-AB






Figure 1



Turbine Shaft Speed Sensor

PTO Models Only = 496-1244 Ohms Resistance Part Number F81Z-7M101-BA

Non PTO Models Only = 781-1979 Ohms Resistance Part Number F81Z-7M101-AA

Output Shaft Speed Sensor

All Models = 781-1979 Ohms Resistance Part Number F81Z-7M101-AA




Figure 2



FORD 4R100 OUTPUT SHAFT SPEED SENSOR ROTOR

Output Shaft Speed Sensor Rotor is press fit to the output shaft and requires new Spacer Tool, Rotunda No. 307-388 for spacing the speed sensor rotor the proper distance from the park gear, if it was removed from the output shaft during service.




Figure 3






Figure 4




4R100 TYPICAL 4 WHEEL DRIVE E4OD 4X4 WITHOUT LUBE PLUG

NO SHOULDER

Copyright © 2005 ATSG

SHOULDER



NOTE: Extension Housings are model sensitive. Refer to Ford Motor Co. parts list for proper part numbers.






Figure 6







Figure 7



Most F-Series vehicles over 8500 GVW equipped with the 4R100 transmission have an external "Oil-To-Air" cooler only. Due to the internal design the "Oil-To-Air" cooler cannot be adequately flushed to remove contaminants, and requires replacement during transmission rebuild.



The only exception is that F-Series vehicles over 8500 GVW equipped with the 5.4L engine also uses a radiator "In-Tank" cooler in addition to the "Oil-To-Air" cooler.





Figure 8


FORD 4R100 VALVE LINE-UPS IN PUMP ASSEMBLY 15 Diesel Engine PWM Only. Gasoline Engine "On-Off" Only. 10 1. Pressure Regulator Valve 2. Spring Retainer 3. Pressure Regulator Outer Spring 4. Pressure Regulator Inner Spring 5. Pressure Regulator Boost Valve 6. Pressure Regulator Boost Valve Sleeve 7. Snap Ring 8. Converter Clutch Regulator Valve 9. Converter Clutch Regulator Spring 10. Converter Clutch Regulator Bore Plug 11. Bore Plug Retainer 12. Converter Clutch Control Valve (Gas "On-Off" Only) 13. Converter Clutch Control Spring (Gas ''On-Off Only) 14. Converter Clutch Control Bore Plug 15. Converter Clutch Control Line-up (Diesel "PWM" Only) Copyright © 2005 ATSG

Figure 9





USED WITH THE "CAST IRON" COAST CLUTCH DRUM WITH 5.4L AND 6.8L "WITHOUT" PTO OPTION



USED WITH THE "STAMPED STEEL" COAST CLUTCH DRUM WITH 5.4L AND 6.8L "WITHOUT" PTO OPTION




Figure 10







Figure 11



STAMPED STEEL MOLDED RUBBER COAST CLUTCH PISTON FOR NEW DESIGN COAST CLUTCH DRUM

NEW DESIGN STAMPED STEEL, MOLDED RUBBER SEAL PISTON OEM PART NUMBER F81Z-7A262-AA







Figure 12








Figure 13






Figure 14






Figure 15






Figure 16






Figure 17






Figure 18



FORD 4R100 MAIN, LOWER, AND ACCUMULATOR VALVE BODY LEGEND

	MAIN, LOWER, AND ACCUMULATOR VALVE BODY LEGEND				
Item	Description	Item	Description		
1	Lower Valve Body	47	Spring Clip Bore Plug Retainer		
2	2 Hex Head Bolt, M1 X 36 (2 Required) 48 Direct Clutch Accumulator Regulat		Direct Clutch Accumulator Regulator Plunger Bore Plug		
3	Retaining Plate	49	Direct Clutch Accumulator Regulator Plunger Spring		
4	Manual 1-2 Transition Valve Spring	50	Direct Clutch Accumulator Regulator Plunger		
5	Manual 1-2 Transition Valve	51	Direct Clutch Accumulator Regulator Valve Retainer		
6	Spring Clip Bore Plug Retainer	52	Direct Clutch Accumulator Regulator Valve Spring		
7	Engagement Valve Bore Plug	53	Direct Clutch Accumulator Regulator Valve		
8	Engagement Valve Spring	54	Spring Clip Bore Plug Retainer		
9	Engagement Valve	55	O.D. Clutch Accumulator Regulator Plunger Bore Plug		
10	Main Valve Body	56	O.D. Clutch Accumulator Regulator Plunger Spring		
11	Checkball 1/4", 2 Required (7E195)	57	O.D. Clutch Accumulator Regulator Plunger		
12	Checkball 5/16", 2 Required (7E195)	58	O.D. Clutch Accumulator Regulator Valve Retainer		
13	Manual Control Valve	59	O.D. Clutch Accumulator Regulator Valve Spring		
14	Manual Valve "E" Clip	60	O.D. Clutch Accumulator Regulator Valve		
15	Spring Clip Bore Plug Retainer	61	Spring Clip Bore Plug Retainer		
16	Low Reverse Modulator Valve Sleeve	62	Int. Clutch Accumulator Regulator Plunger Bore Plug		
17	Low Reverse Modulator Valve Plunger	63	Int. Clutch Accumulator Regulator Plunger Spring		
18	Low Servo Modulator Valve Spring	64	Int. Clutch Accumulator Regulator Plunger		
19	Low Servo Modulator Valve Spring	65	Int. Clutch Accumulator Regulator Valve Retainer		
20	Low Reverse Modulator Valve	66	Int. Clutch Accumulator Regulator Valve Spring		
21	Spring Clip Bore Plug Retainer	67	Int. Clutch Accumulator Regulator Valve		
22	3-4 Shift Valve Bore Plug	68	Spring Clip Bore Plug Retainer		
		_			
23	3-4 Shift Valve Spring 3-4 Shift Valve	69 70	Line Pressure Modulator Plunger Sleeve		
24	· · · · · · · · · · · · · · · · · · ·		Line Pressure Modulator Plunger		
25			Line Pressure Modulator Spring And Retainer Assembly		
26			Line Pressure Modulator Valve Spring		
	27 2-3 Shift Valve 73 Line Pressure Modulator Valve		Line Pressure Modulator Valve		
	28 Retaining Plate				
29	Solenoid Regulator Valve Spring				
30	Solenoid Regulator Valve				
31	Retaining Plate				
32	Coast Clutch Shift Valve Spring				
33	Coast Clutch Shift Valve	\bot			
34	Retaining Plate	\perp			
35	4-3-2 Shift Timing Control Valve Plunger Spring	\bot			
36	4-3-2 Shift Timing Control Valve Plunger				
37	Retaining Plate				
38	4-3-2 Shift Timing Valve				
39	4-3-2 Shift Timing Valve Spring				
40	Spring Clip Bore Plug Retainer				
41	1-2 Shift Valve Bore Plug				
42	1-2 Shift Valve				
43	Drive 2 Valve				
44	1-2 Shift Valve Spring				
46	Accumulator Valve Body (7G422 Model Sensitive)				
			Copyright © 2005 ATSG		



FORD 4R100 SOLENOID RESISTANCE CHARTS

Solenoid Resistance Chart			
Solenoid	Solenoid Body Pin Numbers	Resistance	
Shift Solenoid "B" (2)	1 and 2	20-30 Ohms	
Shift Solenoid ''A'' (1)	1 and 3	20-30 Ohms	
TCC Solenoid, Gasoline (On-Off)	1 and 4	20-30 Ohms	
TCC Solenoid, Diesel (PWM)	1 and 4	10-20 Ohms	
Coast Clutch Solenoid	1 and 5	20-30 Ohms	
Electronic Pressure Control Solenoid	11 and 12	3.0-5.0 Ohms	
Transmission Fluid Temp Sensor	7 and 8	See Chart Below	

Trans	Transmission Fluid Temperature		
• <i>C</i>	• <i>F</i>	Resistance	
-40 to -20	-40 to -4	1062k - 284k W	
-19 to -1	-3 to 31	284k - 100k W	
0 - 20	32-68	<i>100k - 37k</i> W	
21-40	69-104	<i>37k - 16k</i> W	
41-70	105-158	16k - 5k W	
71-90	159-194	<i>5k</i> - 2.7k W	
91-110	195-230	2.7k - 1.5k W	
111-130	231-266	1.5k - 0.8k W	
131-150	267-302	0.8k - 0.54k W	




Figure 20



Shift Solenoid Application Chart					
Selector Lever Commanded Range Gear		Shift Solenoid ''A''	Shift Solenoid ''B''	TCC Solenoid	Coast Clutch Solenoid
P/R/N	1	ON	OFF	*	*
D	1	ON	OFF	*	*
D	2	ON	ON	*	*
D	3	OFF	ON	*	*
D	4	OFF	OFF	*	*
Errst Through 3rd Gear Only, SSA, SSB, TCC, Same as Overdrive, Cancel			e as Overdrive, C	CS Always On.	
MANUAL 2	2	*	*	*	ON
MANUAL 1	2	OFF	OFF	OFF	ON
MANUAL 1	1	ON	OFF	OFF	ON

^{*} Controlled by PCM

SHIFT SOLENOID "A" ALWAYS OFF

	Selector Lever Position			
PCM Gear	(2	1	
Commanded	Act	ual Gear Obt	ained	
1st	4	2	1	
2nd	3	2	2	
3rd	3	2	2	
4th	4	2	2	

SHIFT SOLENOID "B" ALWAYS OFF

	Selector Lever Position			
PCM Gear	①	2	1	
Commanded	Act	ual Gear Obt	ained	
1st	1	2	1	
2nd	1	2	1	
3rd	4	2	2	
4th	4	2	2	

SHIFT SOLENOID "A" ALWAYS ON

	Selector Lever Position			
PCM Gear	(2	1	
Commanded	Act	ual Gear Obt	ained	
1st	1	2	1	
2nd	2	2	1	
3rd	2	2	1	
4th	1	2	1	

SHIFT SOLENOID "B" ALWAYS ON

	Selector Lever Position			
PCM Gear	(D)	2	1	
Commanded	Act	Actual Gear Obta		
1st	2 2		1	
2nd	2	2	1	
3rd	3	2	2	
4th	3	2	2	

Pin No.

1 2

3

4

5

12



Technical Service Information

FORD 4R100 SOLENOID BODY PIN IDENTIFICATION AND FUNCTION VEHICLE HARNESS **SOLENOID BODY CONNECTOR CONNECTOR** (4)(3)(2)**SOLENOID ASSEMBLY** Gasoline Engines Only - Part Number = F81Z-7G391-BA Diesel Engines Only ----- Part Number = F81Z-7G391-AB Copyright © 2004 ATSG

	PCM Conn	ector Pin	
Description	Gas & Diesel (Cal)	Diesel (49 St	
Vehicle Power In For Solenoids (VPWR)	71, 97	71, 97	
Shift Solenoid "B" (2) Ground from PCM	11	1	
Shift Solenoid "A" (1) Ground from PCM	6	27	
Converter Clutch Solenoid Ground from PCM	54	28	

Solenoid Connector Pin Identification and Function

6	Not Used		
7	Transmission Fluid Temp Sensor	37	37
8	Transmission Fluid Temp Sensor (Signal Return)	91	91
9	Not Used		
10	Not Used		
11	Electronic Pressure Control (EPC)	81	81

Coast Clutch Solenoid Ground from PCM

71,97 **Vehicle Power In For EPC Solenoid (VPWR)** 71,97 Figure 22

20

(49 State)

53



1999 FORD 4R100			
Abbreviation Description			
Abbreviation	Description	Abbreviation	Description
4X4L	4X4 Low Switch	MIL	Malfunction Indicator Lamp
ABS	Antilock Brake System	OCT ADJ	Octane Adjust
A/C	Air Conditioning	OSS	Output Shaft Sensor
ACCS	Air Conditioning Clutch Status	PCM	Powertrain Control Module
AP	Accelerator Pedal Position Sensor	PIP	Profile Ignition Pickup
ARPMDES	Ancillary Engine Speed Desired	RPM	Engine Speed
BARO	Barometric Pressure Sensor	SCCS	Speed Control Command Switch
ВОО	Brake ON/OFF Switch	SS1	Shift Solenoid "1"
BPA	Brake Pressure Applied	SS2	Shift Solenoid "2"
BPP	Brake Pedal Position	SSA	Shift Solenoid "A"
CCS	Coast Clutch Solenoid	SSB	Shift Solenoid "B"
СРР	Clutch Pedal Position	SPOUT	Spark Output
CRUISE	Cruise Control Mode (Driving)	TCC	Torque Converter Clutch
DLC	Data Link Connector	TCIL	Trans Control Indicator Lamp
DTC	Diagnostic Trouble Code	TCS	Transmission Control Switch
DTC CNT	Diagnostic Trouble Code Count	TFT	Transmission Fluid Temperature
DTR	Digital Transmission Range Sensor	TP	Throttle Position Sensor
EBP	Exhaust Back Pressure	TSS	Turbine Shaft Speed Sensor
ECT	Engine Coolant Temperature	VPWR	Vehicle Power Supply
EOT	Engine Oil Temperature	VREF	Vehicle Reference Voltage
EPC	Electronic Pressure Control	VSS	Vehicle Speed Sensor
EPR	Exhaust Pressure Regulator	WOT	Wide Open Throttle
FUEL PW	Fuel Pulse Width		
GPC	Glow Plug Control Duty Cycle		
IAT	Intake Air Temperature		
ICP	Injector Control Pressure Sensor		
IPR	Injector Pressure Regulator		
IVS	Idle Validation Switch		
KAM	Keep Alive Memory		
KAPWR	Keep Alive Power		
КОЕО	Key On Engine Off		
КОЕО	Key On Engine Running		
MAF	Mass Air Flow Sensor		
MAP	Manifold Absolute Pressure Sensor		Copyright © 2005 ATSG

Figure 23



1999 FORD 4R100		
Diagnostic Trouble Code Chart		
Diagnostic Code	Description	Symptom
P0102 P0103	MAF sensor system fails to operate in a normal manner, which may cause a transmission concern.	High EPC pressure. Firm shifts and engagements. May flash TCIL.
P0107 P0108	BARO sensor circuit signal higher or lower than expected.	Firm shift feel, late shifts at higher altitudes.
P0122	(TP) Throttle Position sensor or (AP) Accelerator Pedal Position sensor below specification during normal operation.	Harsh engagements, firm shift feel, abnormal shift schedule, abnormal TCC operation or does not engage.
P0123	(TP) Throttle Position sensor or (AP) Accelerator Pedal Position sensor above or below normal specifications during normal operation.	Harsh engagements, firm shift feel, abnormal shift schedule, abnormal TCC operation or does not engage.
P0235	MAP sensor or circuit open, shorted to ground or to 5V.	Firm shift feel, late shifts at higher altitudes.
P0236	MAP sensor signal higher or lower than expected or no response due to vacuum hose circuit damaged, disconnected or restricted.	Firm shift feel, late shifts at higher altitudes.
P0237	MAP sensor out of On-Board Diagnostics range. No response during Dynamic Response (Goose) test.	Rerun On-Board Diagnostics and perform 'Goose' test when asked.
P0340 P0341 P0344	(DI) Distributor Ignition circuit concern or (CKP) Crankshaft Position sensor failure.	Engine will stall or will not run. May flash TCIL.
P0500 P0503	Insufficient or intermittent vehicle speed input from VSS/ABS.	Harsh engagements, firm shift feel, abnormal shift pattern, unexpected downshifts may occur at closed throttle, abnormal TCC operation or engages only at WOT. May flash TCIL.
P0571	(BPP) Brake Pedal Position switch failure, or not connected.	Failed off. TCC will not disengage when brake is applied.
P0703	(BPP) Brake Pedal Position switch failure, or not connected.	Failed off. TCC will not disengage when brake is applied.
P0705	(DTR) Digital Transmission Range sensor circuit malfunction.	Harsh engagements, firm shift feel. May flash TCIL.
P0708	(DTR) Digital Transmission Range sensor circuit malfunction.	Slight increase in EPC pressure.
P0712	TFT sensor circuit grounded, exceeds scale set for temperature of 315°F.	Harsh engagements, firm shift feel, abnormal shift schedule, abnormal TCC operation or does not engage.
		Copyright © 2005 ATSG



	1999 FORD 4R100	
Diagnostic Trouble Code Chart		
Diagnostic Code	Description	Symptom
P0713	TFT sensor circuit open, exceeds scale set for temperature of minus 40°F.	TCC and stabilized shift schedule may be enabled sooner after cold start. May flash TCIL.
P0715	Insufficient input from TSS sensor.	Set DTC, Flash TCIL and Flash MIL.
P0717	TSS sensor signal intermittent.	Set DTC, Flash TCIL.
P0718	TSS sensor signal noisy.	Set DTC.
P0720	Insufficient input from OSS sensor.	Set DTC, Flash TCIL and Flash MIL.
P0721	OSS sensor signal noisy.	Set DTC.
P0722	OSS sensor signal intermittent.	Set DTC, Flash TCIL.
P0731	1-2 shift error because of SSA, SSB, or internal transmission components.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
P0732	2-3 shift error because of SSA, SSB, or internal transmission components.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
P0733	3-4 shift error because of SSA, SSB, or internal transmission components.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
P0741	The PCM picked up an excessive amount of TCC slippage during normal operation.	TCC slippage/erratic or no torque converter clutch operation. Flash TCIL.
P0743	TCC Solenoid circuit failure.	Short Circuit: Engine stalls in "D" or "2" at idle with brake applied. Open Circuit: TCC never engaged.
P0750	SSA circuit failure.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
P0755	SSB circuit failure.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
		Copyright © 2005 ATSG



	1999 FORD 4R100	
Diagnostic Trouble Code Chart		
Diagnostic Code	Description	Symptom
P0781	1-2 shift error because of SSA, SSB, or internal transmission components.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
P0782	2-3 shift error because of SSA, SSB, or internal transmission components.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shif solenoid operation chart.
P0783	3-4 shift error because of SSA, SSB, or internal transmission components.	Improper gear selection depending on failure mode and transmission range selector position. Refer to shift solenoid operation chart.
P1100 P1101	MAF sensor system fails to operate in a normal manner, which may cause a transmission concern.	High EPC pressure. Firm shifts and engagements. May flash TCIL.
P1111	System Pass.	No Codes Detected.
P1120	Throttle Position Sensor voltage lower than expected.	Harsh engagements, firm shift feel abnormal shift schedule, abnorma TCC operation or does not engage.
P1124	Throttle Position Sensor out of On-Board Diagnostics range during KOEO test.	TP sensor (Gas Engines) not at idl position during KOEO test.
P1280	Injection Control Pressure (ICP) sensor circuit failure (Diesel Engine), or out of range low.	May result in firm shifts.
P1281	Injection Control Pressure (ICP) sensor circuit failure (Diesel Engine), or out of range high.	May result in firm shifts.
P1460 P1463 P1464	A/C switch error.	Failed On: EPC pressure slightly low with A/C off. Failed Off: EPC pressure slightly low with A/C on.
P1500	Insufficient or intermittent vehicle speed input from VSS/ABS.	Harsh engagements, firm shift fee abnormal shift pattern, unexpecte downshifts may occur at close throttle, abnormal TCC operation of engages only at WOT. May flas TCIL.
		Copyright © 2005 ATSO



	1999 FORD 4R100	
Diagnostic Trouble Code Chart		
Diagnostic Code	Description	Symptom
P1702	Digital Transmission Range (DTR) sensor signal intermittent.	Erratic harsh shift engagements.
P1703	(BPP) Brake Pedal Position switch not actuated during KOER test.	Failed on or not connected, TCC will not engage at less than one-third throttle opening.
P1704	Digital Transmission Range (DTR) sensor misaligned or failed electronically.	Increase in EPC pressure.
P1705	Digital Transmission Range (DTR) sensor not run in park or neutral during On-Board Diagnostics KOEO or KOER tests.	Rerun On-Board Diagnostics.
P1711	Transmission not at operating temperature during On-Board Diagnostics.	Warm vehicle to normal operating temperature and rerun On-Board Diagnostics.
P1713	No change in TFT sensor - Low range.	May flash TCIL.
P1714	SSA mechanical failure detected.	Improper gear selection depending on failure mode and transmission range selector position. Refer to ship solenoid operation chart.
P1715	SSB mechanical failure detected.	Improper gear selection depending on failure mode and transmission range selector position. Refer to ship solenoid operation chart.
P1718	No change in TFT sensor - High range.	May flash TCIL.
P1728	Excessive amount of transmission slippage has been detected.	Transmission slippage, erratic or no TCC operation. May flash TCIL.
P1729	4X4 Low switch circuit failure.	Early or delayed shift schedule.
P1740	TCC solenoid mechanical failure detected.	Harsh shift, may flash TCIL.
P1744	The PCM picked up an excessive amount of TCC slippage during normal operation.	TCC slippage/erratic or no torque converter clutch operation. Flash
P1746	Failure of the EPC control pressure driver located inside the PCM.	Open circuit causes maximum EPO pressure, harsh engagements and shifts. May flash TCIL.
P1747	EPC shorted circuit failure, or PCM.	Shorted circuit causes minimum EPC pressure, limits engine torqu with partial fuel shut off and heave misfire. Flashing TCIL.
		Copyright © 2005 ATSO



1999 FORD 4R100			
Diagnostic Trouble Code Chart			
Diagnostic Code	Description	Symptom	
P1754	CCS circuit failure.	Failed Off: No third gear engine braking in O.D. cancel. Failed On: Third gear emgine braking in O.D. range. Coast clutch may be damaged causing eventual failure.	
P1760	EPC signal intermittent short.	Short circuit causes minimum EPC pressure.	
P1780	TCS not cycled during the On-Board Diagnostics or the circuit is open or shorted.	No overdrive cancel when switch is cycled.	
P1781	4X4 Low switch circuit failure.	Early or delayed shift schedule.	
P1783	Transmission Fluid Temperature has exceeded 270°F.	Slight increase in EPC pressure. May flash TCIL.	
		Copyright © 2005 ATSG	



FORD 4R100 POWER-TAKE-OFF DESCRIPTION AND OPERATION

DESCRIPTION:

Beginning at the start of production for 1999 models, Ford Motor Company introduced a new 4R100 transmission in some F250, F350, F450 and F550 Super Duty Trucks, equipped with the 5.4L, 6.8L and 7.3L engines. Basically the new 4R100 is a revised version of the previous E4OD transmission with a Power-Take-Off (PTO) window on the left side of the transmission case, right behind the front pump. Refer to Figure 29. The revisions that have occured have created many major engineering changes that have affected many internal and external parts that will create service concerns and diagnostic concerns.

PTO REQUIREMENTS:

- (1) Obviously the case must be PTO capable with the cast-in window in the transmission where the PTO unit mounts to the transmission, as shown in Figure 29.
- (2) Designed for use during Mobile (Some Models) or Stationary conditions.
- (3) PTO is available as an option *only* on 8500 GVW or above, Super Duty F-Series trucks with 6.8L Gasoline and 7.3L Diesel engines. Ford 4R100 transmissions on other models *are not* PTO capable.
- (4) Battery voltage *must* be supplied to the Electronic Engine Control (EEC) input pin 4 on gasoline models, or pin 66 on diesel models, *when PTO is engaged*. The processor uses this information to raise EPC pressure to approximately 55 PSI so that you do not smoke the coast clutch. *This voltage must be provided by the PTO installer.*

CONDITIONS FOR PTO OPERATION (General):

- (1) The vehicle is not in the crank or start mode.
- (2) The transmission range selector *must* be in P, R, O.D, 2 or 1 position. The PTO will not operate when selector is in the neutral position.
- (3) PTO operation is inhibited when in cranking mode, neutral, or 4th gear.
- (4) Transmission only operates 1st through 3rd gears. Computer strategy does not allow 4th gear to engage, even if selected.
- (5) Transmission Fluid Temperature Sensor reading is up to operating temperature.

Continued on Page 36






Figure 29




DIESEL ENGINE PTO OPERATION:

"AUXILIARY" POWERTRAIN CONTROL MODULE 7.3L DIESEL ENGINE (ONLY)

- The Auxiliary Powertrain Control Module (APCM) commands the Electronic Engine Control (EEC) module to increase the idle speed during PTO operation. The APCM controls engine speed from 1200 to 2500 RPM.
- The Auxiliary Powertrain Control Module is a seperate option, *it does not come standard* with a PTO capable transmission, and is for 7.3L diesel applications only.
- Intended for stationary use only, and in stationary operation the PTO requires an engine idle speed of 1200 RPM. During stationary PTO operation on the 7.3L diesel, the EEC increases the idle to 1200 RPM automatically.
- During stationary PTO operation, the Torque Converter Clutch (TCC) engages once the RPM reaches 1200-1300 RPM.
- The following conditions *must* be met before the idle speed is increased:
 - 1. Parking brake must be engaged for all applications.
 - 2. No hydraulic brake actuation.
 - 3. Accelerator pedal must be in the idle position.
 - 4. Vehicle speed must be zero MPH.
 - 5. Brake lights must be functional.





Continued on Page 37

Copyright © 2005 ATSG

Continued on Page



GASOLINE ENGINE PTO OPERATION:

- (1) PTO installer must obtain a "High Idle Throttle Control" from an aftermarket source.
- (2) Auxiliary Powertrain Control Module seen on the previous page, *does not* work on the gasoline engine models. APCM module works *only* on the 7.3L diesel engine.
- (3) For stationary PTO operation, an engine idle speed of 1300 RPM is required.
- (4) The Torque Converter Clutch (TCC) engages once the engine reaches 1300 RPM.

TRANSMISSION FUNCTIONS DURING PTO OPERATION:

- (1) Shift Solenoid "B" (2) is turned on, the coast clutch activates and does not allow 4th gear operation during PTO operation.
- (2) The Electronic Pressure Control (EPC) pressure is raised to approximately 55 PSI. This is why the coast clutch will be smoked in a short period of time if the battery voltage wire is not applied to EEC input pin 4 (gasoline) or pin 66 (diesel) when the PTO is engaged.
- (3) The Transmission Control Indicator Lamp (TCIL) illuminates.
- (4) When the PTO is turned ON, the transmission operates only in 1st through 3rd gears. Overdrive 4th gear is not allowed by the strategy.
- (5) The transmission shift schedule is *early* and shift feel is *very firm*.

DIAGNOSIS CONCERNS WITH PTO EQUIPPED VEHICLES:

- (1) Always ensure that PTO is turned OFF, before any diagnosis procedures begin.
- (2) *Never* perform any transmission special tests (i.e. pressure test, stall test etc.) when the PTO is turned ON.
- (3) If a transmission concern or symptom goes away with the PTO turned OFF, it is most likely *not a transmission concern*.
- (4) On Board Diagnostics operate normally during PTO operation with the exception of the engine misfire moniter. The circuit checks made by the PCM and Failure Mode Effect Management (FMEM) capability will continue. The PTO *must* be turned OFF to access Diagnostic Trouble Codes (DTC's) and perform OBD tests.
- (5) No testing with the PTO turned ON.

Copyright © 2005 ATSG



FORD 4R100 "NON-PTO" AND "PTO"

HYDRAULIC DIFFERENCES

CHANGE: Begining at the start of production for 1999 models, Ford Motor Company made available a "Power Take Off" option for some F250, F350, F450 and F550 Super Duty Trucks, equipped with 5.4L, 6.8L and 7.3L engines.

REASON: The "PTO" option addition, to the 4R100, required many changes to the transmission to make the "PTO" function. The "PTO" window, added to the case, the "PTO" drive gear and other cosmetic changes were previously covered in this manual. Hydraulic changes also had to be made to make the coast clutch operate in ranges other than the Drive ranges.

PARTS AFFECTED:

- (1) *TRANSMISSION CASE:* The transmission case was changed to acommodate the "PTO" window, as previously shown in this manual. All 4R100 Cases, "NON-PTO" and "PTO," also had a "Dam" added to seperate "Rear Lube" and to incorporate "Central Lube" as shown in Figure 30.
- (2) VALVE BODY TO CASE SPACER PLATE: The Valve Body to Case Spacer plate on the "PTO" versions had a hole added, to supply the 3-4 Shift Valve with Line Pressure, as shown in Figure 32. A hole was also added to the Spacer Plate on "NON-PTO" and "PTO" versions to connect "Solenoid Regulator Valve" oil to supply "Central Lubrication." Refer to Figures 31 and 32 for identification of "NON-PTO" and "PTO" Valve Body To Case Spacer Plates.
- (3) *MAIN VALVE BODY:* A passage was added on the "Upper Side" of the Main Valve Body on "PTO" versions, as shown in Figure 34, to supply Line Pressure to the 3-4 Shift Valve. A passage was also added, on the "Lower Side" of the Main Valve Body, to connect the 3-4 Shift Valve (Coast Clutch Circuit) to an exhaust as shown in Figure 36. The spring side of the 3-4 Shift Valve was also seperated from the Low/Reverse circuit as shown in Figure 36. Refer to Figures 33 thru 36 for identification of "NON-PTO" and "PTO" Main Valvebody's.
- (4) *LOWER VALVE BODY:* The Lower Valve Body had a passage added, as shown in Figure 38, to connect to the *''new''* exhaust passage in the Main Valve Body. Refer to Figures 37 and 38 for identification of "NON-PTO" and "PTO" Lower Valvebody's.
- (5) LOWER VALVE BODY SPACER PLATE: The Lower Valve Body Spacer Plate had a hole added to connect the "new" exhaust passage in the Main Valve Body to the "new" exhaust passage in the Lower Valve body, as shown in Figure 39. Refer to Figure 39 for "NON-PTO" and "PTO" Lower Valve Body Spacer Plate identification.

INTERCHANGEABILITY:

None of the parts listed above will interchange between "NON-PTO" and "PTO" versions.

SERVICE INFORMATION:

Valve Body To Case Spacer Plate (Non-	PTO)F81Z-7A008-DA
Valve Body To Case Spacer Plate (PTO))F81Z-7A008-BA

Partial Hydraulic Schematic is provided for you in Figure 40 on Page 49.

Copyright © 2005 ATSG






Figure 30






Figure 31






Figure 32






Figure 33






Figure 34






Figure 35

ATSG




Figure 36






Figure 37






Figure 38







Figure 39








Figure 40



FORD 4R100 "PWM" AND "NON-PWM" PUMP DIFFERENCES

CHANGE: Beginning at the start of production in 1999, the 4R100 transmission was offered with two different torque converter clutch application strategies. A "PWM" (Pulse Width Modulated) version, was added in V-10 gas powered vehicles and all diesel, and a "NON-PWM" version, offered in all other gas powered vehicles. This required two different solenoid packs as well as two different pump assemblies.

REASON: For smooth converter apply on V-10 gas and diesel engine models.

PARTS AFFECTED:

(1) PUMPASSEMBLY:

- The pump cover assembly had the rear of the Converter Clutch Valve bore enlarged approximately .070" to acommodate the enlarged land of the Converter Clutch Valve, as shown in Figure 41.

 A .036" orifice and an air bleed were added to the TCC Solenoid signal passage, as shown in Figure
- 43.
 - The Converter Clutch Control Valve's rear spool was enlarged approximately .070". There was
- also a bushing and valve added to the end of the valve train, as shown in Figure 41.
 - A hole was added to the pump cover to connect the Converter Clutch Control Valve Bushing to
- Converter Regulator Valve oil, as shown in Figure 43.
 - The Converter release orifice in the NON-PWM pump cover, as shown in Figure 42, was removed
- from the PWM pump cover, as shown in Figure 43.
 - Refer to Figure 44 for the NON-PWM pump hydraulic circuit.
 - Refer to Figure 45 for the PWM pump hydraulic circuit with all hydraulic changes shown.

SOLENOID PACK:

- The PWM solenoid pack requires a Pulse Width Modulated torque converter clutch solenoid and the NON-PWM solenoid pack requires an on-off torque converter clutch solenoid.
- Refer to Figure 46 to identify the differences between the two solenoid packs.

INTERCHANGABILITY:

None of the parts listed above are interchangable from model to model.

SERVICE INFORMATION:

"NON-PWM" Pump assy. (with "Cast Iron" coast clutch drum)	F81Z-7A103-AA
"NON-PWM" Pump assy. (with "Stamped Steel" coast clutch drum)	
"PWM" Pump assy. (with "Stamped Steel" coast clutch drum)	
"NON-PWM" Solenoid Pack	
"PWM" Solenoid Pack	F817-7G391-AR

Copyright © 2005 ATSG






Figure 41






Figure 42






Figure 43






Figure 44






Figure 45




FORD 4R100

SOLENOID RESISTANCE CHARTS

Solenoid Resistance Chart		
Solenoid	Solenoid Body Pin Numbers	Resistance
Shift Solenoid ''B'' (2)	1 and 2	20-30 Ohms
Shift Solenoid "A" (1)	1 and 3	20-30 Ohms
TCC Solenoid, On-Off (NON-PWM)	1 and 4	20-30 Ohms
TCC Solenoid, Diesel & V10 (PWM)	1 and 4	10-20 Ohms
Coast Clutch Solenoid	1 and 5	20-30 Ohms
Electronic Pressure Control Solenoid	11 and 12	3.0-5.0 Ohms
Transmission Fluid Temp Sensor	7 and 8	Variable

SOLENOID BODY CONNECTOR






Figure 46



FORD E4OD/4R100 NEW DESIGN 6 PINION FORWARD AND REVERSE PLANETARY CARRIER

CHANGE: Beginning at the start of production for all 1998 model E4OD transmissions, *some models* will be equipped with a new design 6 pinion forward planetary carrier (See Figure 47), and a new design 6 pinion reverse planetary carrier (See Figure 48).

REASON: Increased torque carrying capacity and increased planetary carrier durability.

PARTS AFFECTED:

- (1) FORWARD PLANETARY CARRIER Now has 6 pinions instead of the previous 4 pinions for increased torque carrying capacity and increased durability (See Figure 47).
- (2) REVERSE PLANETARY CARRIER Now has 6 pinions instead of the previous 4 pinions for increased torque carrying capacity and increased durability (See Figure 48).

INTERCHANGEABILITY:

The new design forward planetary carrier *will back service all models* of the E4OD, but it *does require* the latest design forward ring gear hub and bearing assembly, as there are no holes for the previous design thrust washer (See Figure 47).

The new design reverse planetary carrier *will back service all models* of the E4OD, but it *does require* the latest design reverse clutch hub and three tang thrust washer for *both* sides, of the planetary carrier as shown in Figure 48.

SERVICE INFORMATION:

Forward Planetary Carrier (6 Pinion)F81Z-7A398-CA
Reverse Planetary Carrier (6 Pinior	n)F81Z-7D006-AA

Copyright © 2005 ATSG








Figure 47



NEW DESIGN 6 PINION REVERSE PLANETARY CARRIER PART NUMBER F81Z-7D006-AA




Front View




Rear View

REQUIRES 1997-UP DESIGN LEVEL REVERSE CLUTCH HUB ASSEMBLY



REQUIRES 3 TANG THRUST WASHERS ON BOTH SIDES OF REAR CARRIER PART NUMBER F0TZ-7A166-D



Copyright © 2005 ATSG

Figure 48



FORD E4OD/4R100 NEW DESIGN SUN SHELL

CHANGE: There is now a new design Sun Shell with "Tabs" added to the center of the sun shell slots, as shown in Figure 49, implemented by Ford Motor Co. as a running change, during the 2000 model year. This change eliminated the need for the number 8 thrust washer between the forward and direct drums.

REASON: Main reason for this change was cost savings and ease of assembly.

PARTS AFFECTED:

- (1) INPUT SUN SHELL New design have "Tabs" added to the center of the sun shell slots, as shown in Figure 49, which now support the direct drum for the required clearance between the direct and forward clutch housings, and allows elimination of the number 8 thrust washer, as shown in Figure 50.
- (2) DIRECT CLUTCH HOUSING Manufactured "Without" slots in the center hub, as they were no longer needed to accept the number 8 thrust washer tabs. Both design direct drums are illustrated in Figure 50, and cut-away in Figure 51.
- (3) NUMBER 8 THRUST WASHER Eliminated (See Figure 50 and 51).

INTERCHANGEABILITY:

The 1st design Sun Shell is no longer available from Ford Motor Co, as the 2nd design Sun Shell *will* retro-fit back on all models, with or without the number 8 thrust washer.

The 2nd design Direct Clutch Housing (No Slots For Washer) *must* be used with the 2nd design Sun Shell, as there are no accommodations for the number 8 thrust washer.

Refer to "Service Information" below for current OEM part numbers.

SERVICE INFORMATION:

Direct Clutch Housing, 2nd Design (Without 4 Tab Washer)	YC3Z-7D044-BA
Direct Clutch Housing, 1st Design (With 4 Tab Washer)	F81Z-7D044-BA
Sun Shell, Hardened, 2nd Design	YC3Z-7D064-BA
Sun Shell, Regular, 2nd Design	YC3Z-7D064-AA
Direct to Forward Drum (No. 8) 4 Tab Thrust Washer	

Copyright © 2005 ATSG






Figure 49







Figure 50




PREVIOUS DESIGN DIRECT CLUTCH DRUM "WITH" SLOTS FOR THE NUMBER 8 THRUST WASHER AND PREVIOUS SUNSHELL

When Direct Clutch Housing Is Not Supported Here,



NEW DESIGN DIRECT CLUTCH DRUM "WITHOUT" SLOTS FOR THE NUMBER 8 THRUST WASHER AND NEW SUNSHELL

> When Direct Clutch Housing Is Supported By The "Added" Raised Tabs Here,



 $Copyright © 2005 \ ATSG$



INTERMEDIATE FORDE 4R100WHEEL FAILURE

COMPLAINT: Some Ford Motor Company vehicles equipped with the 4R100 transmission may exhibit

premature failure of the newly introduced Intermediate "Diode" Freewheel device that was

installed in model year 2001 and illustrated in Figure 52.

CAUSE: The cause may be, more than expected load factors.

CORRECTION: The Intermediate "Diode" is *no longer serviced* by Ford Motor Company. The part number now supercedes to all of the previous design level parts, which include the direct clutch housing, intermediate sprag assembly, outer race to direct drum thrust washer, and the intermediate friction plates. All of the previous design level parts are illustrated in Figure 53, with the OEM part numbers. The intermediate frictions must be replaced because the tooth count on the outer race between the diode and the sprag are different.

Special Note: ATSG recommends replacing the Intermediate 'Diode' during service, even if it has not yet failed, to protect yourself from possible future failures.

SERVICE INFORMATION:

Direct Clutch Housing, 2nd Design (Without 4 Tab Washer)	
Direct Clutch Housing, 1st Design (With 4 Tab Washer)	F81Z-7D044-BA
Sun Shell, Hardened, 2nd Design	
Sun Shell, Regular, 2nd Design	YC3Z-7D064-BA
Direct to Forward Drum 4 Tab Thrust Washer	E9TZ-7C096-A
Direct Drum to Outer Sprag Race Thrust Washer	E9TZ-7G401-A
Intermediate Sprag Assembly	E9TZ-7A089-B
Intermediate Friction Plates (Special 50 Tooth, 3 Required)	1C3Z-7B164-BA




Figure 52






Figure 53



FORD 4R100 HYDRAULIC PASSAGE IDENTIFICATION

The following pages provide you with hydraulic passage identification in Figure 55 through Figure 64 for the transmission case, all valve bodies and all oil pump configurations. The legend for the abbreviations is found in Figure 54.

PASSAGE IDENTIFICATION LEGEND
1-R = 1st-Reverse
1-R/M2 = 1st-Reverse/Manual 2
C-CL = Coast Clutch
CONV = Converter
D-CL = Direct Clutch
EPC = Electronic Pressure Control
EX = Exhaust
F-CL = Forward Clutch
INT-CL = Intermediate Clutch
L/R-CL = Low/Reverse Clutch
M123/R = Manual 1, 2, 3/Reverse
OD = Overdrive
OD234 = Overdrive 2nd, 3rd, 4th
OD34/R = Overdrive 3rd, 4th/Reverse
PRN1 = Park, Reverse, Neutral, 1st
PRN1/M2 = Park, Reverse, Neutral, 1st/Manual 2
R/1 = Reverse/1st
R/M2 = Reverse/Manual 2
R/M2/S2 = Reverse/Manual 2/Solenoid 2
R = Reverse
S1 = Solenoid 1
S2 = Solenoid 2
S3 = Solenoid 3
S4 = Solenoid 4
S4/1-R/M2 = Solenoid 4/1st-Reverse/Manual 2
SRV = Solenoid Regulator Valve
Copyright © 2005 ATSG

Figure 54






Figure 55






Figure 56






Figure 57






Figure 58






Figure 59






Figure 60




Figure 61






Figure 62






Figure 63






Figure 64



FORD MOTOR COMPANY TRUCKS 1996 AND LATER

NO TORQUE CONVERTER CLUTCH APPLICATION AT LESS THAN 30 PERCENT THROTTLE

- **COMPLAINT:** Some Ford Motor Company Trucks, 1996 and later, may exhibit a no Torque Converter Clutch application at less than 30 percent throttle. No Trouble Codes present.
- CAUSE NO. 1: One cause for this condition may be that one or more of the vehicle brake light bulbs, including the High Mount brake light may be burned out, or have a damaged filament (See Figure 65). When this condition is present, the PCM will detect an open in the brake lamp circuit, and due to a pull-up resistor in the PCM, will output voltage from PCM terminal 92 to the brake on-off switch (See Figure 66). As a result, the Torque Converter Clutch will not be applied at less than 30 percent throttle.
- CAUSE NO. 2: Recently there has been an increase in the popularity of replacing the stock incandescent brake lamp bulbs, with aftermarket LED lamp assemblies. Refer to Figures 67 and 68. The main advantages of switching to LED lamp assemblies is that there are no fragile filaments to burn out or break, which means that the LED lamp assemblies may possibly last for the entire life of the vehicle, and LED lamps consume much less energy than the stock incandescent bulbs. Due to the low power consumption, the PCM *may* view this reduced current draw as being a burned out bulb, resulting in a no Torque Converter Clutch apply at less than 30 percent throttle.

CORRECTION NO. 1:

Prior to any part replacement or modifications, it would be recommended to check for a 5 to 8 volt DC signal coming out of the PCM at terminal 92 using a volt meter set to read DC voltage. Voltage may also be checked at the Light Green wire located at the back of the Brake On-Off Switch. *Note: The example given is for a 1996 F-Series 7.3 Diesel.* This test will help to confirm that a circuit fault has been detected by the PCM. Refer to Figure 66. *Normal operation will be 0 volts DC, brake off, and 12 volts DC, brake on.*

Replace any burned out brake lamp bulbs, including the High Mount brake lamp bulb, as shown in Figure 65. It is also important to note, that a bad ground for the rear lamp assembly, has also been known to cause the identical symptom. Refer to Figure 69 for the rear lamp assemblies ground location.

CORRECTION NO. 2:

For those vehicles that have had the stock incandescent bulbs replaced with aftermarket LED bulb assemblies, it *may* be necessary to install a 6 ohm- 50 watt Load Resistor across the brake light power wire to simulate the load of the regular stock incandescent bulb (See Figure 70). *Note: One resistor is required for use on each LED bulb assembly.*

The 6 ohm, 50 watt Load Resistors are available from the suppliers of the LED bulb assemblies. Two examples are "superbrightleds.com" and "digikey.com". Cost of the resistor is approximately five dollars U.S.






Figure 65





Figure 66








Figure 67 Figure 68




Figure 69






Figure 70







FORD E40D/4R100

NEW "SPECIAL" CASE ASSEMBLY FROM FORD MOTOR CO.

CHANGE: Currently, the "only" new case available from Ford Motor Company, for replacement in any E4OD equipped vehicles, is a modified 4R100 case. Ford has machined out the dam in the case that seperates center and rear lube, near the rear of the case, as shown in Figure 71.

CAUTION: This case **requires** special main spacer plate, spacer plate gaskets, speed sensor plugs and extension housing, that **do not** come with the new case from Ford Motor Company.

We have provided you with a list of additional parts that will be required to use this case, under "Parts Affected", depending on the model year that you are repairing. The older the unit, the more parts required.

REASON: Cost savings due to not having to maintain seperate dies for the case assemblies.

PARTS AFFECTED:

REQUIREMENTS FOR 1996 THRU 1998 MODELS ONLY:

- (1) SPACER PLATE Ford Motor Co. part number F81Z-7A008-EA or F8UZ-7A008-CA, as shown in Figure 72.
- (2) CASE TO SPACER PLATE GASKET Ford Motor Co. part number F81Z-7C155-AA, with "White" stripe for identification, as shown in Figure 73.
- (3) SPACER PLATE TO V.B. GASKET Ford Motor Co. part number F81Z-7D100-AB, with "Blue" stripe for identification, as shown in Figure 73.
- (4) COOLER BYPASS ASSEMBLY Ford Motor Co. part number F81Z-7H322-AA for 1996 models only, as shown in Figure 74. 1997 and 1998 models came with cooler bypass.
- (5) SPEED SENSOR PLUG Ford Motor Co. part number F81Z-7H183-AA, and 2 are required, as shown in Figure 75.
- (6) LUBE ORIFICE PLUG Ford Motor Co. part number F81Z-7E380-AA, which should come with the new case from Ford, as shown in Figure 76.
- (7) EXTENSION HOUSING A4R100 style with boss in the extension housing to retain the lube plug in the new design case, as shown in Figure 76.

Continued on next Page



PARTS AFFECTED (Cont'd):

REQUIREMENTS FOR 1989 THRU 1995 MODELS ONLY:

- (1) SPACER PLATE Ford Motor Co. part number F81Z-7A008-EA or F8UZ-7A008-CA, as shown in Figure 72.
- (2) CASE TO SPACER PLATE GASKET Ford Motor Co. part number F81Z-7C155-AA, with "White" stripe for identification, as shown in Figure 73.
- (3) SPACER PLATE TO V.B. GASKET Ford Motor Co. part number F81Z-7D100-AB, with "Blue" stripe for identification, as shown in Figure 73.
- (4) COOLER BYPASS ASSEMBLY Ford Motor Co. part number F81Z-7H322-AA, as shown in Figure 74.
- (5) SPEED SENSOR PLUG Ford Motor Co. part number F81Z-7H183-AA, and 2 are required, as shown in Figure 75.
- (6) LUBE ORIFICE PLUG Ford Motor Co. part number F81Z-7E380-AA, which should come with the new case from Ford, as shown in Figure 76.
- (7) EXTENSION HOUSING A4R100 style with boss in the extension housing to retain the lube plug in the new design case, as shown in Figure 76.
- (8) MAIN VALVE BODY Requires 1996 hydraulics which is identified by RF-F6 cast into the valve body, in location shown in Figure 77, and checkball locations are shown in Figure 78.
- (9) LOWER VALVE BODY Requires 1996 hydraulics which is identified by RF-F6 cast into the lower valve body, in location shown in Figure 77.
- (10) LOWER VALVE BODY SPACER PLATE The 1996 hydraulics version which is identified by the 2 holes for bathtub checkball and 3 small holes, as shown in Figure 77.
- (11) ACCUMULATOR VALVE BODY Requires 1996 hydraulics which is identified by RF-F6 cast into the accumulator valve body and slot cast shut, as shown in Figure 77.
- (12) CASE CHECKBALL LOCATIONS Requires the 1996 and later case checkball locations, which is eight checkballs in locations shown in Figure 79.

INTERCHANGEABILITY:

Parts that have been mis-matched, depending on what you have done, can create;

- Harsh Shifts
- No Overdrive
- ●Bind in Manual 1

- Lack of Lube
- Bind in Reverse Slip in Reverse

SERVICE INFORMATION:

Main Valve Body Spacer Plate	F81Z-7A008-EA
Main Valve Body Spacer Plate (Optional)	
Case To Spacer Plate Gasket (White Stripe)	F81Z-7C155-AA
Spacer Plate To Valve Body Gasket (Blue Stripe)	F81Z-7D100-AB
Cooler Bypass Assembly	F81Z-7H322-AA
Speed Sensor Plugs (2 Required)	F81Z-7H183-AA
Lube Orifice Plug (Comes with new case)	






Figure 71

"SPECIAL" MAIN SPACER PLATE REQUIRED FOR MODIFIED 4R100 CASE 0 0 Φ . 0 0 0 0 0 F81P-DA F81P-EA Use Part Number For Identification F81Z-7D008-EA Copyright © 2005 ATSG

Figure 72






Figure 73






Figure 74




Figure 75






Figure 76



VALVE BODY CASTINGS REQUIRED FOR MODIFIED 4R100 CASE REQUIRED LOWER I.D.-ROUGH FORGING **VALVE BODY** NUMBER OF "RF-F6" WHICH INDICATES "96" MODEL "Two" Holes Over The Bathtub REQUIRED LOWER **VALVE BODY** SPACER PLATE 00 0000 000 0 THREE "SMALL" HOLES Identification One "V" Notch I.D.-ROUGH FORGING NUMBER OF "RF-F6" WHICH INDICATES "96" MODEL **REQUIRED MAIN** VALVE BODY O(0)I.D.-ROUGH FORGING NUMBER OF "RF-F6" WHICH INDICATES "96" MODEL **REQUIRED ACCUMULATOR** VALVE BODY Copyright © 2005 ATSG

Figure 77

ProCarManuals.com



Technical Service Information

VALVE BODY CHECKBALL LOCATIONS REQUIRED FOR MODIFIED 4R100 CASE

VALVE BODY CHECKBALL LOCATIONS REQUIRES THREE 1/4" RUBBER BALLS, AND TWO 5/16" RUBBER BALLS




Figure 78






Figure 79







Figure 80



ACCUMULATOR BODY PASSAGE IDENTIFICATION








Figure 82






Figure 83






Figure 84



THE REAL SCOOP ON FORD'S 4R100 POWER TAKE OFF OPERATION

BY: JIM DIAL TECHNICAL CONSULTANT FOR ATSG

In the last two years we have discussed in bulletins and seminars about all of the changes the 4R100 had to go through to be able to drive a "Power Take Off" (PTO) unit. This article is the real scoop on how the whole system operates electronically and hydraulically.

Dale England and I had an opportunity to check out a 1999 Ford F550 Super Duty truck equipped with a 7.3 "Powerstroke" diesel. This vehicle had just been fitted with a PTO, to drive a pump, to run a "bucket type lift" for T.V. cable repair. We thought that this would be a great time to clear up some questions that we were curious about. The first question that needed to be answered was, What does the Powertrain Control Module (PCM) do when the "PTO" is turned on? Before we could answer that question, we had to find out how 12 volts was supplied to terminal 66 at the PCM. This was something we covered in last years seminar. We discussed how the technician, that was installing the PTO, had to supply their own 12 volt power source to terminal 66 on diesel models or terminal 4 on gas models, to tell the PCM when the PTO mode was selected. We decided to check terminal 66 of the PCM where we found a Blue with a Yellow stripe wire that headed back in towards the cab. We followed the wire under the column area, as shown in Figure 1, and found a tag that was taped to the wire that stated "PTO Enable." This wire is supplied by Ford, which is information we were not sure of before. The company that installed the PTO on this truck, had set up their own relay that was wired so there would be "no" voltage supplied to terminal 66 until the selector is in the Park position and the Parking brake is "on." This is an obvious safety precaution.

It was now time to find out the shift solenoid strategy, now that terminal 66 was handled. We proceeded to hook up some test equipment to the solenoid pack to monitor the PCM signals and we placed the selector in Park and set the Parking brake. I started the vehicle and reached up and pushed the PTO button......nothing happened. GREAT!.....it worked before we touched it, famous last words! The first thing we thought wasmaybe we disturbed a connection along the way to terminal 66. We checked all of our conections and verified 12 volts at terminal 66, with the PTO button "on", and still nothing. After screwing around for half an hour we decided to swallow our pride and call the person that installed the PTO. He came to the phone and we told him about the problem and what we had done. The first thing out of his mouth was, "did anyone , by chance, disconnect the batteries for any reason?" My jaw hit the floor......when we checked terminal 66 at the PCM we had to disconnect the batteries so we could unplug the connector from the PCM safely. Long story short, the PCM must have a 7 mile drive cycle at speeds over 50 mph. before it remembers that it is capable of running a PTO! Well, needless to say, we felt like complete idiots! and yes, that fixed it. So...... now after wasting all of this time, we placed the selector in Park and set the Parking brake. When the PTO button was depressed the following things happened:

- •The PCM turned the no.2 solenoid "ON"
- The OD Cancel Light came on and the Coast Clutch Solenoid was turned "ON"
- The PCM brought engine rpm up to approximately 1500. (Powerstroke diesels are "Drive By Wire" as in they have NO throttle cable).
- EPC pressure rose to about 55psi
- When engine idle hit about 1500 rpm the TCC solenoid came on.

All of this happened within a few seconds. In Figure 2 we have provided a partial hydraulic circuit diagram to show some of the hydraulic changes that had to be made to the 3-4 shift valve and why these changes were necessary. As you can se, the 3-4 shift valve is now connected to line pressure






Figure 1






Figure 2

